

SAFE HOME, LEADSAFE CHARLOTTE

CITY OF CHARLOTTE

HOUSING & NEIGHBORHOOD SERVICES

BID OPENING CERTIFICATON RECORD

Date of Bid Walk: FEBRUARY 13,2020 (12 PM) Due Date: FEBRUARY 20 @ 2 PM_

HNS <u>20-51</u> 5430 AMITY PLACE

Public Body Estimate

Address	PBE Amount	PBE -15%	+15%
5430 AMITY PLACE	#38214.20	#32.481	#43946.
		,	, ,

Bid Results

Addresses	Bidder 1	Bidder 2	Bidder 3	Bidder 4	Bidder 5
	YESHUAS	JP GROUP	SCHULTZ	AVM	MALONE
5430 AMITY PLACE	442,125.00	# 44.245.°°		42080.00	
		, ,		\	

Bid Walk Attendees

YESHUAS BUILDERS	JP GROUP	SCHULTZ	
AVM CONTRACTORS	MALONE		

This is to certify that bids for the job identified aboye were publicly opened and read aloud in the Neighborhood & Business Service
Office located at 600 E. Trade Street, Charlotte, NC
Bids Opened By: J. KATHOO / KATHOO Bids Recorded By: J. M. Motton
Witnessed By: Pate: FBRUARY 20, 2020
Witnessed By: Date: Date: Date: No LO
Note: Responsive bids are those which fall within a range of 15% above and 15% below the public body cost estimate. As a

general rule, the lowest responsive bid is recommended to the property owner for consideration.



SAFE HOME

CITY OF CHARLOTTE

HOUSING & NEIGHBORHOOD SERIVCES

Contractor Award Recommendation Sheet
ADDRESS: 5430 AMITY PLACE
ADDRESS: 5430 AMITY PLACE Recommended Contractor AVM
Contract is not recommended due to:
Attach Bid Sheet and Bids
 has 4/03 950. \$ amount of work 3 jobs in the pipeline is current on all projects, has no outstanding punch list items is in good standing with the City of Charlotte is not on any debarred lists
RS certifies that Contractor: is eligible and application and credentials have been verified by Amanda is lowest responsible bidder has specified any material changes or substitutions is not the lowest bidder, but other bidders are not responsible due
Insert or attach Photograph of JOB BOARD:
· ATTACHED - FULL BOARD INDIVIDUAL SELECTED.
Signed:

		٠.,	:			
S	PM Street Amount Statffinal pm street Pinant Date JM S. Summit 3490 1127-311 EL Columbus \$ 36,000 1/28-3/31	Merriman 7,200 5/0H5dalet 40,850 2/7-3/8 Estingham 5,900 (3) St. Mark (01,000	Street Punumt start Finish GTB Col Flint* 31, 20c 2/10-3/15 PM Street	altralay mount state and street from the stree	PM Street Amount street Amount street Amount street	
Schultz		Fairgreen Newland Thinked Springs		The Say 360	T (c) marken (c) T	

ال 113-2121 312-417 He 2-4/6 34,350 PINOUNT 36,760 27,735 SL6/14 Dinglewood* (a) Natson Dublink Street LE THE



SAFE HOME

CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES .

above due date and time.

Company Acknowledgement:	
provisions of the housing improvement funded through the City of Charlotte fully inspected the site in all particulars the time stated and in strict accordance any and all labor and materials, and to the advised respective contractual, for All labor, materials, services and each on the Drawings and in the Specific	quipment necessary for the completion of the Work shown
Specs Dated: 02/04/2020	Number of Pages: 8
Addenda # 1 Dated:	Number of Pages:
Addenda # 2 Dated:	Number of Pages:
Project Schedule: Minimum Start Date	°-41412020
Completion Deadline:	511 12020

Please Print and Sign:	
Company Name/Firm: AVM Contractors	ŝ
Authorized Representative Name:	Michalesko
Signature:	Date: 2/20/20

Response Due: 2/20/2020 2:00 PM

Prepared By:
City of Charlotte Housing & Neighborhood Services
600 E. Trade Street
Charlotte, NC 28202
(704) 336-7600

Property Details							
Address:	5430 Amity Place	. (Owner:	Vivlan	Robinson		
	Charlotte, NC 28212	C	Owner Phone:	Home	Home: (704) 569-0938		
Structure Type:	Single Unit	F	rogram(s): .		Healthy Homes Tested- NO LEAD SH2019 Eligible HOME FY19		
Square Feet:	1671						
Year Built:	1964						
Property Value:			•				
Tax Parcel:	13362611		•				
Census Tract:	•						
Property Zone:	Council District 5	•					
Additional Commen	ts						
BIDWALK ON THURSE	DAY 2-13 AT NOON						
Repairs							
<u>Description</u>				<u>Floor</u>	Room		<u>Exterior</u>
Cabinet Repair				`	KITCHE	1	
Repair base cabinet und	der kitchen sink by installing plywood b	ottom. Finis	h with white se	mi-glos	s low-VOC	paint.	
		Bid Cost:		Х		. =	¥50
	·		Base		Quantity		Total Cost
Counter Tops Replace			the terms of the second of the		KITCHE	V	221 317 11 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Screw to base cabinet a adjoining walls with low	a square edged plastic laminate counte VOC caulking to match wall color. Ow	r top. Provi ner's choice	de end-caps ar of in-stock col	nd cutou lor and t	it for sink. exture.	Caulk c	ounter top to
		Bid Cost	, !	х		_=_	850
			Base		Quantity		Total Cost
Double Bowl Sink Cor	nplete				KITCHE	 N	
rated at 2.0 GPM or les	(22" x 8" double bowl, stainless steel, s s, with a 15 year drlp- free warranty, P es. No copper compression fittlngs.	elf rimming -trap, supply	kitchen sink ind / lines, full port	cluding ball typ	a single ha e shut-off \	ndle me valves 8	tal body faucet, escutcheon plates
	`	Bid Cost	:	Х		=	650
•			Base	olde Sees	Quantity	V.CV	Total Cost

 -		AA A 88	-	

KITCHEN

nstall a flush mounted, ground fault circuit interrupted, duple	•			
	Bid Cost:		Х	350
		Base	Quantity	Total Cost
ange Hood Exterior Vented	e esta a transfer de la marcia de	2 8 2 7 ° 4 ° 4 ° 6 ° 6 ° 6 ° 6 ° 6 ° 6 ° 6 ° 6	KITCHEI	V
stall an exterior ducted enameled range hood with integral abinet with screws. Include metal vent and roof or wall cap	l controls and light o/damper assembl	capable of /, using #14	100 cfm at 70 son copper Romex.	es. Attach hood to Owner's choice of color.
	Bid Cost:		X	= 650
		Base	Quantity	Total Cost
rep & Paint Room Semi Gloss	, gyong duang ti di inag da a militar	eyeata ya di di da asa	BATHRO	OOM- MASTER
th owner's choice of low VOC acrylic SEMI-GLOSS latex. ardware, flxtures and accessories. Any moving of furniture			nu any associated	Tulini. Naplace of uncov
·			**	
	Bid Cost:	Base	Quantity	Total Cost
•		Base	BATHRO	DOM- MASTER
epair wall finish. Patch drywall or plaster holes in wall grea		Base	BATHRO	DOM- MASTER
tepair wall finish. Patch drywall or plaster holes in wall grea		Base	BATHRO	DOM- MASTER esh and mud over the
epair wall finish. Patch drywall or plaster holes in wall grea		Base All others u	BATHR(se an adhesive m	DOM- MASTER esh and mud over the
tepair wall finish. Patch drywall or plaster holes in wall grea	ater than one inch	Base	BATHRO	DOM- MASTER esh and mud over the
epair wall finish. Patch drywall or plaster holes in wall greatesh with the appropriate material. Wet sand smooth.	ater than one inch	Base All others u	BATHROSE an adhesive m	DOM- MASTER esh and mud over the
Repair wall finish. Patch drywall or plaster holes in wall greatnesh with the appropriate material. Wet sand smooth. Light Fixture Replace Replace or install a ceiling mounted 2 bulb or wall mounted	ater than one inch	Base All others u Base	BATHROSE an adhesive modern with the second	DOM- MASTER esh and mud over the = 650 Total Cost
Repair wall finish. Patch drywall or plaster holes in wall greatnesh with the appropriate material. Wet sand smooth. Light Fixture Replace Replace or install a ceiling mounted 2 bulb or wall mounted	Bid Cost:	Base Base Base	BATHROSE an adhesive modern with the second	DOM- MASTER esh and mud over the = 650 Total Cost
epair wall finish. Patch drywall or plaster holes in wall greatesh with the appropriate material. Wet sand smooth. ight Fixture Replace eplace or install a ceiling mounted 2 bulb or wall mounted Light fixture over Vanity.	ater than one inch	Base Base Base	BATHRO se an adhesive m X Quantity BATHRO D light fixture with	DOM- MASTER esh and mud over the = 650 Total Cost
epair wall finish. Patch drywall or plaster holes in wall greatesh with the appropriate material. Wet sand smooth. ight Fixture Replace teplace or install a ceiling mounted 2 bulb or wall mounted Light fixture over Vanity.	Bid Cost:	Base All others u	BATHROSE AN Adhesive modern adhesive modern adhesive modern and adhesive modern adhesive moder	DOM- MASTER esh and mud over the = 650 Total Cost DOM- MASTER in shade and lamps.
Repair wall finish. Patch drywall or plaster holes in wall greatnesh with the appropriate material. Wet sand smooth. Light Fixture Replace Replace or install a ceiling mounted 2 bulb or wall mounted Light fixture over Vanity.	Bid Cost:	Base Base Base Base Base	BATHRO se an adhesive m X Quantity BATHRO D light fixture with X Quantity	E USO Total Cost OOM- MASTER a shade and lamps. E USO Total Cost OOM- MASTER Total Cost
Vall Finish Repair Repair wall finish. Patch drywall or plaster holes in wall greatesh with the appropriate material. Wet sand smooth. Light Fixture Replace Replace or install a ceiling mounted 2 bulb or wall mounted Light fixture over Vanity. GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, dup	Bid Cost:	Base Base Deproved, LE	BATHRO se an adhesive m X Quantity BATHRO D light fixture with X Quantity	E USO Total Cost OOM- MASTER a shade and lamps. E USO Total Cost OOM- MASTER Total Cost

17" Height Commode Replace

BATHROOM- MASTER

Install a 17" height, 2 piece, close coupled, white, vitreous china commode with a maximum water usage per flush of 1.6 gallons. Include plastic or pressed wood white seat, supply pipe, shut-off valve, flap valve and wax seal.

	Bid Cost:	>	· (= 400		
		Base	Quantity	Total Cost		
Steel Bathtub - Remove and Replace	re boot to	BATHROOM- MASTER				
Install a 5' white, enameled, formed steel bathtub complete with waste, single lever tub/shower diverter with water-saving show		surface, lever	operated pop-up	o drain and overflow, PVC		
	Bid Cost:	,	х	= 850		
	•	Base	Quantity	Total Cost		
Ceramic Wall Tile		ad a transfer	BATHRO	OOM- MASTER		
Install owner's choice ceramic wall tile over cement fiberboard trimmer pieces to complete installation. After at least 24 hours grout and apply mildew resistant white silicone caulk at all sear	drying time, ap	ply latex base	d portland cemei	ase, cap, stop, return and nt grout. Clean all excess		
	Bid Cost:		х	= 1, 330		
• ,		Base	Quantity	' Total Cost		
Vanity/ Counter Top/ Sink			BATHRO	OOM- MASTER		
Install new vanity cabinet complete with counter top of laminat single handled metal faucet with drain and pop-up., P- trap, su Vanity medicine cabinet/mirror to remain.	e with vitreous pply lines, full (china sink or r port ball type s	narble-lite top wi hut-off valves &	ith preformed sink. Include escutcheon plates.		
	Bld Cost:		х	= 850		
		Base	Quantity			
Bath Mirror			BATHRO	DOM- MASTER		
Install mirror sized at the width of vanity by 36" high. Use adhe	esive manufacti	ured for this pu	rpose and apply	/ to sound backing.		
	Did G A		V	- 250		
	Bid Cost: _	Base	Quantity	Total Cost		
Ceramic Tile Install	Lander Committee of the	иен (¹¹¹ — Д. 1. 11. 1.	BATHRO	DOM- MASTER		
Install ceramic tile previously removed for floor system replace specifications. Include transitions and painted or stained wood	ement using ce d quarter-round	ramic tile that i I at all perimet	matches existing ers to complete i) per manufacturer's installation.		
•	Bid Cost: _		х	= 750		
		Base	Quantity	Total Cost		
a programme for the first program of the control of the first section of the control of the cont	tivo imperation (record to b	green to greater court to a	and the contract of the part of		

17" Height Commode Replace

BATHROOM - HALF

Install a 17" height, 2 piece, close coupled, white, vitreous china commode with a maximum water usage per flush of 1.6 gallons. Include plastic or pressed wood white seat, supply pipe, shut-off valve, flap valve and wax seal.

	Bid Cost:		х	= 050
•		Base	Quantity	Total Cost
Vanity/ Counter Top/ Sink	e to the time less than		BATHRO	OM - HALF
install new vanity cabinet complete with counter top of lamin single handled metal faucet with drain and pop-up., P- trap, Vanity medicine cabinet/mirror to remain.	ate with vitreous o supply lines, full p	shina sink or r ort ball type s	marble-lite top with hut-off valves & e	ı preformed sink, Include scutcheon plates.
	Bid Cost:		X	= 650
		Base	Quantity	Total Cost
GFCI Receptacle 20 AMP			BATHRO	OM - HALF
Install a flush mounted, ground fault oircuit interrupted, duple	ex receptacle and	cover plate. I	ish wire and repa	ir all tear out as needed.
	Bld Cost:		Х	= 325
	Based 1990	Base	Quantity	Total Cost
Prep & Paint Room Semi Gloss	eren eren eren er er en ere	1. 1	BATHRO	OM - HALF
Remove or cover hardware and accessories not to be painted fungus, dirt, and dust from surfaces. Fill holes and cracks. F with owner's choice of low VOC acrylic SEMI-GLOSS latex. hardware, fixtures and accessories. Any moving of furniture	rime all new mate Painting shall Ind required shall be	orials and spo Slude walls an Included.	t prime existing w id any associated	lth acrylic latex. Top coat
	Bld Cost:	Base	<u>۸</u> Quantity	Total Cost
Light Fixture Replace				
Replace or install a ceiling mounted 2 bulb or wall mounted * Light Fixture over vanity.	4 bulb strip, UL a	pproved, LEI	O light fixture with	shade and lamps.
	Bld Cost:		Χ .	<u>.</u> 150
	-	Base	Quantity	Total Cost
Light Fixture Replace			BEDROC	
Replace or install a ceiling mounted 2 bulb or wall mounted	4 bulb strip, UL a	pproved, .LEI	D light fixture with	shade and lamps.
	Rid Coets		. X	= 200
	DIU 0031	Base	Quantity	Total Cost
Exterminate Insects	en e a camera e e comunidada.	alan yang alam serser	GEN REC	
Exterminate for insects. Include a one year warranty. All ex	termination shall t	e performed	by a licensed con	ractor.
	Bid Cost: _		X	450
	Ela Cost:	Base	Quantity	Total Cost
Work Specification - City of Charlotte Housing & Neighborh				2/4/2020 4

Exterminate Termites

Exterminate for termites. Drill and patch foundation and pavement where necessary. Exterminator must be licensed and provide a 1	
year guarantee with an optional yearly renewable warranty for the homeowner.	

GEN REQ

	Bid Cost:	Ж	· · · · · · · · · · · · · · · · · · ·	- 1100
		Base	Quantity	Total Cost
moke Detector Hard Wired	e geografians for a few fore	anamori y trasti	GEN REQ	
nstall UL approved, interconnected, celling mounted smo attery backups in bedrooms and outside of sleeping are	oke and heat detecto as.	rs permanently	wired into a rec	eptacle boxes with
	Bld Cost:		(= 800
		Base	Quantity	Total Cost
combination CO / Smoke Detector Hard Wired	The second secon		GEN REC	
nstall a hard wired combination carbon monoxide and sr	noke detector with ba	attery back.up.		
	Bid Cost:		‹	= 350
-		Base	Quantity	Total Cost
Electric Service 200 AMP			GEN REC))
Replace electrical service with new 200 amp, main disco	nnect, 110/220 volt,	24 circuit pane	l board, meter so	ocket, weather head,
service cable, ground rods and cable. Include replacem	ent of all sub-panels.	Caulk exterior	service penetral	lon.
service cable, ground rods and cable. Include replacem	ent of all sub-panels.	Caulk exterior	service penetral	4.000
service cable, ground rods and cable. Include replacem	ent of all sub-panels.	Caulk exterior	service penetral	ion.
service cable, ground rods and cable. Include replacem	ent of all sub-panels.	Caulk exterior	service penetra	Total Cost
service cable, ground rods and cable. Include replacem Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throu	ent of all sub-panels. Bid Cost:	Caulk exterior Base	Quantity GEN REC	Total Cost
service cable, ground rods and cable. Include replacem Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throu	ent of all sub-panels. Bid Cost: ghout entire house.	Base Use code appr	Quantity GEN REC	Total Cost
Replace all receptacles, switches and cover plates throu	ent of all sub-panels. Bid Cost:	Base Use code appr	Quantity GEN REC	Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates through or ceiling damage repairs.	ent of all sub-panels. Bid Cost: ghout entire house.	Base Use code appr	Quantity GEN REC	Total Cost Total Cost This also includes ar Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throuwall or ceiling damage repairs. Miscellaneous Plumbing Scope	ent of all sub-panels. Bid Cost: ghout entire house. Bid Cost:	Base Use code appr	Quantity GEN REC ropriate devices.	Total Cost Total Cost This also includes ar Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throuwall or ceiling damage repairs. Miscellaneous Plumbing Scope	ent of all sub-panels. Bid Cost: ghout entire house. Bid Cost: Req.***	Base Use code appr	Quantity GEN RECTORISED CONTRACTORISED CONTRACTORI	Total Cost Total Cost This also includes ar Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throuwall or ceiling damage repairs. Miscellaneous Plumbing Scope	ent of all sub-panels. Bid Cost: ghout entire house. Bid Cost:	Base Use code appr	Quantity GEN REC ropriate devices.	Total Cost Total Cost This also includes ar Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates through a cover plates through a cover plate and cove	ent of all sub-panels. Bid Cost: ghout entire house. Bid Cost: Req.***	Base Base	Quantity GEN REC copriate devices. Quantity FOUND C	Total Cost Total Cost Total Cost Total Cost Total Cost Total Cost Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates through all or ceiling damage repairs. Miscellaneous Plumbing Scope ***Install new sump pump in crawl space area to Code F	ent of all sub-panels. Bid Cost: ghout entire house. Bid Cost: Req.***	Base Base Base Base	Quantity GEN REC Opriate devices. Quantity FOUND C	Total Cost Total Cost Total Cost Total Cost Total Cost Total Cost Total Cost
Replace Receptacles, Switches, and Plates Replace all receptacles, switches and cover plates throuwall or ceiling damage repairs. Miscellaneous Plumbing Scope ***Install new sump pump in crawl space area to Code F Crawl Space Access Door Install a 3/4" pressure treated plywood access door in a	ent of all sub-panels. Bid Cost: ghout entire house. Bid Cost: Req.***	Base Base Base Base Base Base	Quantity GEN REC Opriate devices. Quantity FOUND C	Total Cost Total Cost Total Cost Total Cost Total Cost Total Cost Total Cost

Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Finish. Owner's choice of color stain-finish Bid Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-Ewindows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and palnit. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4,200 Base Quantity Total Cost	Foundation Vent Screen			FOUND CF	RAWL
Carpet & Pad Contractor to move furniture as required to complete carpet installation and return furniture. Remove existing carpet, pad, tack strips and metal edge strips to a code legal dump. Clean Harrkwood floors. Apply filish as needed. Owner's choice of color-stain. Bid Cost: X = 500 Base Quantity Total Cost Carpet & Pad Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a cost of protective Finish. Owner's choice of color stain-finish. Etal Cost: X = 1, 200 Base Quantity Total Cost HEALTHY HOMES Chimney -Structural Support. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. Repair sliding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens, insulate rough opening, install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC costed alturninum coil as needed. Repair all areas disturbed by removal and hetallation. This installation is to include repairing any damaged header, framing to include king studs, jack study study, such study study. Such control installation is to include repairing any damaged header, framing to include king studs, jack study study. Such removal and hetallation. This installation is to include repairing any damaged header, framing to include king studs, jack study study. Total Cost Bid Cost: X = EXTERIOR Total Cost Fower Wash Stding Total Cost Exterior Bid Cost: X = EXTERIOR Total Cost Bid Cost: X = EXTERIOR Total Cost For Exterior trim to be wra	Replace foundation vent housing with heavy duty galvanize	d steel screening.			
Carpet & Pad Contractor to move furniture as required to complete carpet installation and return furniture. Remove existing carpet, pad, tack strips and metal edge strips to a code legal dump. Clean Harrkwood floors. Apply filish as needed. Owner's choice of color-stain. Bid Cost: X = 500 Base Quantity Total Cost Carpet & Pad Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a cost of protective Finish. Owner's choice of color stain-finish. Etal Cost: X = 1, 200 Base Quantity Total Cost HEALTHY HOMES Chimney -Structural Support. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. Repair sliding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens, insulate rough opening, install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC costed alturninum coil as needed. Repair all areas disturbed by removal and hetallation. This installation is to include repairing any damaged header, framing to include king studs, jack study study, such study study. Such control installation is to include repairing any damaged header, framing to include king studs, jack study study. Such removal and hetallation. This installation is to include repairing any damaged header, framing to include king studs, jack study study. Total Cost Bid Cost: X = EXTERIOR Total Cost Fower Wash Stding Total Cost Exterior Bid Cost: X = EXTERIOR Total Cost Bid Cost: X = EXTERIOR Total Cost For Exterior trim to be wra		Rid Coets	>	· {	= 550
Carpet & Pad Contractor to move furniture as required to complete carpet installation and return furniture. Remove existing carpet, pad, tack strips and metal edge strips to a code legal dump. Clean Hardwood floors. Apply finish as needed. Owner's choice of color-stain. Bid Cost: X = 500 Base Quantity Total Cost LIVING ROOM Exterior Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Finish. Owner's choice of color stain-finish Bid Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support Chimney -Structural support for Chimney. Chimney has pulled away from house structure. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Chimney has pulled away from house structure. Bid Cost: X = 1,200 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and still as needed, prime and paint. Exterior time to be wrapped in PVC coated alumihum coil as needed. Repair all areas disturbed by premay and histallation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 47,000 Base Quantity Total Cost Fower Wash Stding EXTERIOR Exterior		bid Cost			Total Cost
and metal adge strips to a code legal dump. Clean Hardwood floors . Apply finish as needed. Owner's choice of color-stain. Bid Cost: X = 500 Base Quantity Total Cost Carpet & Pad LIVING ROOM Exterior Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips an metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Finish. Owner's choice of color stein-finish. Bid Cost: X = 1,200 Base Quantity Total Cost Chimney-Structural Support. Chimney-Structural Support for Chimney. Chimney has pulled away from house structure, repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window Exterior Exterior time to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Power Wash Siding Exterior Exterior Total Cost Base Quantity Total Cost Exterior Total Cost Base Quantity Total Cost Exterior Total Cost Exterior Total Cost Total Cost Base Quantity Total Cost Exterior Total Cost Exterior Total Cost Total Cost Base Quantity Total Cost Exterior Total Cost Power Wash Siding Exterior Total Cost	Carpet & Pad		er geren betar de a		e neg sac e esca america
Carpet & Pad Carpet & Pad Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, stack strips an metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Finlsh. Owner's choice of color stain-finlsh Bad Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4, 200 Base Quantity Total Cost Base Quantity Total Cost EXTERIOR Exterior Final Cost Base Quantity Total Cost Base Quantity Total Cost	and metal edge strips to a code legal dump. Clean Hardwood floors . Apply finish as needed.	i Installation and re	turn furniture,	Remove existing	carpet, pad, tack strips
Carpet & Pad Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective FinIsh. Owner's choice of color stain-finIsh. Bid Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, jlosts, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4,000 Base Quantity Total Cost Base Quantity Total Cost EXTERIOR Exterior Base Quantity Total Cost		Bid Cost:		Κ	<u> 500</u>
Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Finish. Owner's choice of color stain-finish Bid Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support Inspect and correct structural support for Chimney. Chimney has pulled away from house structure, repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4, 200 Base Quantity Total Cost Power Wash Siding Exterior				Quantity	Total Cost
Contractor to move furniture as required to complete carpet removal and return furniture. Remove existing carpet, pad, tack strips are metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Finish. Owner's choice of color stain-finish Bid Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support. HEALTHY HOMES Inspect and correct structural support for Chimney, Chimney has pulled away from house structure, repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, cashing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4, 200 Base Quantity Total Cost EXERIOR EXTERIOR Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior Exterior	Carnet & Pad			LIVING RO	DOM Exterio
Bid Cost: X = 1,200 Base Quantity Total Cost Chimney -Structural Support. HEALTHY HOMES Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. repair slding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-Ewindows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4,200 Base Quantity Total Cost Power Wash Siding EXTERIOR Exterior Exterior trim to be surgered in a bathroom for the properties of the propert	Contractor to move furniture as required to complete carpe metal edge strips to a code legal dump. Clean all hardwood floors and apply a coat of protective Fire		rn furniture. Re	emove existing ca	rpet, pad, tack strips an
Chimney -Structural Support. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure, repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of Window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4, 200 Base Quantity Total Cost Power Wash Siding Exterior Exterior	Owner's choice of color stain-inform				1.200
Chimney -Structural Support. Inspect and correct structural support for Chimney. Chimney has pulled away from house structure, repair siding and trim to make weatherproof. Bid Cost: X = 4.000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4, 200 Base Quantity Total Cost Power Wash Siding Exterior Exterior		Bid Cost: _			
Inspect and correct structural support for Chimney. Chimney has pulled away from house structure. repair siding and trim to make weatherproof. Bid Cost: X = 4,000 Base Quantity Total Cost Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4,200 Base Quantity Total Cost Power Wash Siding EXTERIOR Exterior			Base	Quantity	Total Cost
Chimney has pulled away from house structure, repair siding and trim to make weatherproof. Bid Cost:	Chimney -Structural Support.			HEALTHY	'HOMES
Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X EXTERIOR Exterior Total Cost Power Wash Siding	Chimney has pulled away from house structure.				
Vinyl Window EXTERIOR Exterior Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X EXTERIOR Exterior Total Cost Power Wash Siding		Bid Coet		X	= 4.000
Dispose of window units and any security bars. Field measure, order and Install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4, 200 Base Quantity Total Cost Power Wash Siding EXTERIOR Exterior		Did Gost			Total Cost
Dispose of window units and any security bars. Field measure, order and install new Energy Star rated vinyl, double glazed LOW-E windows including half screens. Insulate rough opening. Install new extension jambs, casing and sill as needed, prime and paint. Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack studs etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4,200 Base Quantity Total Cost Power Wash Siding Exterior	Word Window		****	EXTERIO	R Exterio
Exterior trim to be wrapped in PVC coated aluminum coil as needed. Repair all areas disturbed by removal and installation. This installation is to include repairing any damaged header, framing (to include king studs, jack stude etc.) sub-floor, floor joists, band joists and sill. Any windows replaced in a bathroom must have tempered glass. Bid Cost: X = 4,200 Base Quantity Total Cost Power Wash Siding Exterior	Dispose of window units and any security bars. Field meas	sure, order and ins	tall new Energ	y Star rated vinyl,	double glazed LOW- E
Power Wash Siding Exterior	Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra	ns needed, Repair Iming (to include k	all areas distu ing studs, jack	bed by removal a studs etc.) sub-flo	and installation. This oor, floor joists, band
Power Wash Siding Exterior		Bid Cost:		Х	= 4,200
Power Wash Siding Exterior			Base	Quantity	Total Cost
	·	Access there is a contract to the	* Am * * * *		
	-	ng high pressure w	vater and deter	rgent mix. Adjust _l	pressure to eliminate

Base

Quantity

800

Total Cost

Saamlage	Aluminum	Gutter &	Downspouts	- Install

EXTERIOR

Exterior

Install K- type .027 gauge seamless aluminum gutter to service roof with sufficient pitch to downspouts. White or brown color choice by owner.

by dwildt.				1
	Bid Cost:	x		1850
		Base	Quantity	Total Cost
Prehung Metal Door Entrance	, , , , , , , , , , , , , , , , , , , ,	.1.41	EXTERIOR	Exterior
Remove existing door, frame and threshold. Install new Endead bolt and lever handled door hardware keyed alike. Instally primer and topcoat. This installation to include repair floor joists and sill.	stall wide peep sigh	it, New casing	and shoe molding w	ill match existing.
	Bid Cost:)	(<u> </u>	1200
		Base	Quantity	Total Cost
Aluminum Storm Door	e examenta e v	. ,	EXTERIOR	Exterior
Install an aluminum combination storm and screen door. C * Front,Rear and Side doors.	omplete with self c	oser and locki	ng hardware.	
	Bid Cost:)	(=	425
		Base	Quantity	Total Cost
Light Fixture Exterior			EXTERIOR	Exterior
Replace or install a UL approved, LED light fixture.				
	Bld Cost:)	(=	150
	D14 00011	Base	Quantity	Total Cost
Concrete Step Install	· · · · · · · · · · · · · · · · · · ·	,	EXTERIOR	Exterior
Install concrete step off of patio/stoop, poured over wire m non-slip surface. Dimensions of step must be constructed		ep sȟould be tr	roweled and broom-f	inished to provide a
	Bid Cost:	,	K =	550
		Base	Quantity	Total Cost
Sliding Glass Patio Door	· . · · ···, j· · · · · · · · · · · · · · ·	ing an act a sector	EXTERIOR	Exterior
Remove and dispose of existing door, frame and threshold screen and locking hardware. Insulate cavity. New casing any damaged header, door framing, wall framing, sub-floo	and shoe molding	will match exist	e-hung exterior vinyl ting. This installation	siding patio door with is to include repairing
				10-
	Bid Cost: _	3	Κ , =	1850

Install Handrails			Front porch	Exterior
Install Code approved handrails.				
	Bid Cost:	Х	= (150
			Quantity	Total Cost
Install Handrails			Rear Porch	Exterior
Install Code approved handrails.				•
				850
	Bid Cost:		Quantity	Total Cost
Repoint Masonry Bricks	5.4.1011 . O	1-1-4- 44-1	Rear Porch	Exterior
Rake out existing mortar joints to a minimum depth	of 1/2". Completely fill mortar	joints to match 6	existing.	and the same of th
	Bid Cost:	Х	long to the state of the state	<u> 550</u>
and the second control of the second control			Quantity	Total Cost
Ceramic Wall Tile	er venterals in the more afterness in the second of	יין בייתיה יו	Kitchen	eran dia di tri sare felleri derina
Install owner's choice ceramic wall tile over cementrimmer pieces to complete installation. After at least grout and apply mildew resistant white silicone causes.	st 24 hours drying time, apply l	atex based portl	and cement grou	
	Bid Cost:	X	=	050
Anna Carlos Constantinos de la companya de la comp	E	Base	Quantity	Total Cost
All Contractor's Project Requirements		,		
The contractor is responsible for project requireme	nts, including but limited to:			
Obtaining all permits required. Said permits shall in	nclude all items in this scope of	work.		,
Provide temporary toilet facilities from job start unti	il the completion of work.	•		
Provide AS MANY roll-off dumpsters as needed wi Remove dumpster and repair any evidence of the				
	Bid Cost:	x		1500
	Ĭ	Base	Quantity	Total Cost
Certification			•	
Contractor Name: AVM Confra	actor LCC	and the state of t	Total Cost:	12,080
Signature:			Date: 2/	120/20
Work Specification - City of Charlotte Housing & N		no abore to anno esta e esta anno		2/4/2020 8